

KHITLA, SOIL/MUROM TEMPORARY QUARRY (M.L. AREA 1.26HECT.)

DISASTER MANAGEMENT AND RISK ASSESSMENT:

This being a small scale mine, chances of risk of any accident or disaster is negligible. This is an opencast mine and problem of land slide is negligible in the area. The other incidents related to underground mines are not applicable in this case.

A first-aid box and a stretcher shall be kept at the mine site (in case of any eventuality/ accident that occurs) office of mines manager. Mines manager will make necessary arrangements at the time of any mishap. At the time of any eventuality mine manager will give first- aid treatment to the miner/person injured during mining activity; simultaneously will also inform DGMS. In case of casualty DGMS has to be informed first; at the same time he should see that site of accident is not tampered till the competent authority from DGMS inspect the site. Mines manager should see that the injured persons are admitted in the hospital.