

RISK ASSESMENT
OF
CHAMPANER STONE QUARRY (CRUSHER)

Surface mining involves winning of minerals, transportation, and processing. Risk assessment is identification of points of accidents and takes preventive measures.

Quarry Lease Details:-

1	Name of applicant	M/s Brij Gopal Construction Company Pvt. Ltd. Shri. Yogesh Agrawal
2	Address	R/o:- KD-54 Pitampura North West, Delhi.
3	Applicant's Mobile Number	8085835055
4	Lease Area	2.915 hectare
5	Khasra No.	186/2
6	Village	Champaner
7	Tehsil	Sultanpur
8	District	Raisen
9	State	Madhya Pradesh
10	Lease Period	10Years
11	Proposed Annual Production	90630 Cub. M. per year

High risk accidents may be common in big and underground mines but it cannot be ignore totally in open cast small mines also. Champaner Stone (Crusher) Quarry is having total sanction lease area of 2.915 hectare. It is a open cast mine in which manual and semi mechanized method of mining will be adopted. It is a small scale mine, probability of accident or disasters are almost negligible. It is located in undulating ground covered with hard Basalt stone. There is no any risk of landslide.

